

TECHNICAL DATA SHEET

OLD MASTERS® WIPING STAIN

AVAILABLE SIZES: Half-pint (16), Quart (04), Gallon (01) and 5 Gallon (05)

PRODUCT CODES: 111 Natural Tint Base 117 Early American 123 Fruitwood 129 Pecan

> 112 Golden Oak 118 Dark Mahogany 124 Pickling White 130 American Walnut 113 Cherry 119 Cedar 126 Aged Oak 149 Crimson Fire 114 Red Mahogany 127 Weathered Wood 150 Rich Mahogany 120 Dark Walnut 115 Provincial 121 Special Walnut 125 Puritan Pine 151 Vintage Burgundy

116 Maple 128 Natural Walnut 122 Spanish Oak 152 Espresso

PRODUCT DESCRIPTION: Old Masters® Wiping Stain is a cutting edge, robust interior oil-based stain for use on wood, fiberglass, coated metal and composition surfaces. This product is intended for interior use

only.

SURFACE PREPARATION: All surfaces must be clean, dry and free from dirt, wax, grease, glue and other contaminants or penetration and adhesion will be affected. Wood surfaces must be sanded smooth. Remove dust with a tack rag or a lint-free cloth dampened with mineral spirits. Surface defects should be repaired with an appropriate patching material.

> WARNING! If you scrape, sand or remove old paint, you may release lead dust. LEAD IS TOXIC. EXPOSURE TO LEAD DUST CAN CAUSE SERIOUS ILLNESS, SUCH AS BRAIN DAMAGE, ESPECIALLY IN CHILDREN. PREGNANT WOMEN SHOULD ALSO AVOID EXPOSURE. Wear a NIOSH approved respirator to control lead exposure. Clean up carefully with a HEPA vacuum and a wet mop. Before you start, find out how to protect yourself and your family by contacting the National Lead Information Hotline at 1-800-424-LEAD or log on to www.epa.gov/lead.

APPLICATION: Stir thoroughly before and during application for even distribution of color. Stain application varies based on surface material. Always test stain in an inconspicuous area.

> Application on Bare Wood (used as a stain): Color of stain will vary depending on wood type and porosity and method of application. After cleaning wood surface, sand with #120 or #180 sandpaper until smooth. Remove sanding dust. Apply stain liberally with brush, lint-free cloth or spray until surface is completely wet. Allow to penetrate for 5 to 15 minutes. Wipe with a soft cloth, first across the grain, then with the grain. For a darker color, re-stain when first coat is dry. For a lighter color, wipe with a cloth dampened with paint thinner before the stain has dried.

> Application on Fiberglass & Composition Surfaces: Stain one section or panel at a time. Apply a liberal coat of Wiping Stain with a firm synthetic brush or lint-free rag and work the stain across and into the grain uniformly, feathering out streaks while stain is wet. Wipe brush often on a lintfree rag to remove excess stain.

> Application over Painted Surfaces (used as a glaze): Apply to thoroughly dry paint with cheesecloth or brush, using long, smooth strokes for simulated woodgraining, or blend gently from edges for other effects. Allow the stain to set up approximately 5 to 10 minutes, then dry brush to subdue or blend. Allow stain to dry thoroughly (usually 12 hours or longer, depending on humidity and drying conditions). We do not recommend a lacquer-type finish over a glaze application.

> Application over Previously Finished Surfaces: Lightly sand surface with very fine grit sandpaper or #0000 steel wool. Remove dust with a lint-free cloth or tack rag. With a foam or bristle brush, apply a thin uniform coat of Wiping Stain. Using a soft, dry bristle brush, make light, even strokes in the direction of the grain while allowing the grain pattern beneath the surface to show through. Continue to lightly brush the surface until the pattern is consistent and then allow the stain to dry. If you need to darken the color, apply an additional coat of stain in the same manner as the first coat. Allow stain to dry thoroughly (usually 12 hours or longer, depending on humidity and drying conditions).



TECHNICAL DATA SHEET

OLD MASTERS® WIPING STAIN

MIXING AND TINTING: You can achieve custom colors by intermixing colors or by adding up to 10 ounces of universal

or industrial colorant per gallon. The amount of colorant added may aff ect its performance and

extend dry time. Stir for uniform consistency. DO NOT THIN.

COVERAGE: Approximately 500 square feet per gallon. Spreading rate will vary significantly depending on the

porosity and texture of the wood.

APPLICATION: Approximately 10 hours, depending on humidity, temperature and air movement. Dry times may

also be extended due to excess stain application or lack of stain penetration. Wiping Stain can be topcoated after 12 hours, but stain must be thoroughly dry. When used on hardwood floors, allow 24 hours or longer depending on surface and drying conditions. Ideal drying conditions

recommended are 70° to 75°F and 35 to 50% humidity.

CLEAN UP: Using a cleaning solvent, such as paint thinner or mineral spirits, is recommended for clean up.

The use of paint thinners or mineral spirits may violate VOC compliancy in your area. Check with

your local government agencies to ensure proper compliancy.

To avoid spontaneous combustion during temporary storage, soak soiled rags and waste

immediately after use in a water-filled, closed metal container.

RECOMMENDED FINISH We recommend Old Masters® clear finishes. However, this stain can be topcoated with most

COAT: clears. If a lacquer topcoat is desired, we suggest testing for compatibility before using. When

applying water-based finishes allow a minimum of 24 hours before topcoating.

MAX VOC: 250 grams/liter (2 lbs/gal)

TECHNICAL DATA

FLASH POINT: 102°F Tag Closed Cup **SOLIDS BY WEIGHT:** 33.7% to 45.8%

VISCOSITY AT 77 °: 25 to 27 sec. Ford Cup #2 SOLIDS BY VOLUME: 29.4% to 30.2%

> **AVFRAGE DRY TIME** V.O.C.: 250 grams/liter Approximately 10 hours @ 70°F AND 50% R.H.:

THEORETICAL Not Applicable COVERAGE @ Mil DFT:

VEHICLE: Oil

COVERAGE @ RECOMMENDED Do not thin. Not Applicable

RECOMMENDED DFT Used as packaged. THINNER:

RECOMMENDED

Not Applicable DFT PER COAT:

WEIGHT PER GALLON: 6.9 to 8.5 lbs

> Limited Warranty Since Old Masters® does not control the application of its products, nor is the condition of the surface to which they are applied, a Limited Warranty provided. If the products to not perform as specified, for whatever reason, Old Masters® liability will under no circumstances exceed the replacement of the product.